

# How Winspect can make you and your data look good



## Question # 3

**Q:** How easy is it to annotate and make measurements on images?

**A:** It is a very simple process to add text labels and measurement annotations to an image. You can quickly measure both linear and dB amplitudes and such attributes as; length, width, area, max, min, range, average, deviation and volume. Simply draw a box, polygon, circle, ellipse, vector or point and select any or all measurements. Annotations are saved with the image and can be printed as part of a report.



## Question # 14

**Q:** What kinds of reporting options are available?

**A:** Reports printed from Winspect contain the scan image, annotations and any additional information you specify, such as header, axis, and scale information. You can even generate reports automatically using Microsoft Word. These automated reports use templates that take an image, perform calculations on it and then generate a complete report. Contact UTEX for more information.

To see the other questions in this series, please visit [www.utex.com](http://www.utex.com) or call us at: Tel (905) 828-1313 Fax (905) 828-0360 E-mail [sales@utex.com](mailto:sales@utex.com)